



BTW 6.3.0.4400

Release Notes

April 07, 2010

Confidential and Proprietary Information

© Broadcom Corp., 2008, All rights reserved.
Printed in United States of America.
16340 West Bernardo Drive
San Diego, CA 92127
Phone: (858) 385-8800
Fax: (858) 385-8810

LICENSED SOFTWARE

©200x Broadcom Corporation

This program is the proprietary software of Broadcom Corporation and/or its licensors, and may only be used, duplicated, modified or distributed pursuant to the terms and conditions of a separate, written license agreement executed between you and Broadcom (an "Authorized License"). Except as set forth in an Authorized License, Broadcom grants no license (express or implied), right to use, or waiver of any kind with respect to the Software, and Broadcom expressly reserves all rights in and to the Software and all intellectual property rights therein. IF YOU HAVE NO AUTHORIZED LICENSE, THEN YOU HAVE NO RIGHT TO USE THIS SOFTWARE IN ANY WAY, AND SHOULD IMMEDIATELY NOTIFY BROADCOM AND DISCONTINUE ALL USE OF THE SOFTWARE.

Except as expressly set forth in the Authorized License,

1. This program, including its structure, sequence and organization, constitutes the valuable trade secrets of Broadcom, and you shall use all reasonable efforts to protect the confidentiality thereof, and to use this information only in connection with your use of Broadcom integrated circuit products.
2. TO THE MAXIMUM EXTENT PERMITTED BY LAW, THE SOFTWARE IS PROVIDED "AS IS" AND WITH ALL FAULTS AND BROADCOM MAKES NO PROMISES, REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS, IMPLIED, STATUTORY, OR OTHERWISE, WITH RESPECT TO THE SOFTWARE. BROADCOM SPECIFICALLY DISCLAIMS ANY AND ALL IMPLIED WARRANTIES OF TITLE, MERCHANTABILITY, NONINFRINGEMENT, FITNESS FOR A PARTICULAR PURPOSE, LACK OF VIRUSES, ACCURACY OR COMPLETENESS, QUIET ENJOYMENT, QUIET POSSESSION OR CORRESPONDENCE TO DESCRIPTION. YOU ASSUME THE ENTIRE RISK ARISING OUT OF USE OR PERFORMANCE OF THE SOFTWARE.
3. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL BROADCOM OR ITS LICENSORS BE LIABLE FOR (i) CONSEQUENTIAL, INCIDENTAL, SPECIAL, INDIRECT, OR EXEMPLARY DAMAGES WHATSOEVER ARISING OUT OF OR IN ANY WAY RELATING TO YOUR USE OF OR INABILITY TO USE THE SOFTWARE EVEN IF BROADCOM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES; OR (ii) ANY AMOUNT IN EXCESS OF THE AMOUNT ACTUALLY PAID FOR THE SOFTWARE ITSELF OR U.S. \$1, WHICHEVER IS GREATER. THESE LIMITATIONS SHALL APPLY NOTWITHSTANDING ANY FAILURE OF ESSENTIAL PURPOSE OF ANY LIMITED REMEDY.

INTRODUCTION

replace

CUSTOMER SUPPORT PORTAL (CSP)

Customers can submit enhancements, changes and/or defects against releases of software or firmware via the Broadcom Customer Support Portal (CSP). CSP cases are replicated into the Broadcom Bluetooth engineering change management database for review by the engineering community and change control boards.

If your project or program is not listed inside the CSP please contact your Broadcom representative whom can configure the CSP system for use with your unique needs.

To start using the CSP please visit <http://support.broadcom.com>.

Installation Command Line Options

To install BTW from command line prompt or from a batch file, use the following command line options:

Setup.exe [/qn | /qb | /qr] [/nw] [/nodfu] [/L<LangId>] [/ru] [/ri]

/qn - Silent install without any UI and user interaction

/qb - Silent install with basic UI with progress dialog without any user interaction

/qr - Silent install with full UI without any user interaction

/nw- Setup.exe does not wait for BTW install to complete, exits after invoking MSI install.

/nodfu- Do not execute DFU during BTW install (even if configured for DFU in SvcPack.ini file)

/noinf - Do not install USB inf file, bcbtums*.inf for Vista and btwusb.inf for XP. (Newly added since 5.5.0.900 and 6.1.0.2800)

/L -Installation language

<LangId> can be one of the following

1033: English

1046: Portuguese (Brazilian)

1028: Chinese Tradition

2052: Chinese Simplified

1030: Danish

1043: Dutch

1035: Finnish

1036: French

1031: German

1040: Italian

1041: Japanese

1042: Korean

1044: Norwegian

1034: Spanish

1053: Swedish

1049: Russian

1045: Polish

14337: Arabic

1029: Czech

1032: Greek

1037: Hebrew

1050: Croatian

1038: Hungarian

2070: Portuguese (European)

1048: Romanian

1055: Turkish

/ru - Suppress reboot at the end of uninstall. (Relevant for Windows 98 and ME during upgrade)

/ri - Suppress reboot at the end of install (Relevant for Windows 98 and ME and if reboot is required on Windows 2000).

For example, to install silently without any UI in German language, use the following command line

setup.exe /qn /L1031

Signed Driver Report

Folder: q:\BTW\btw1.2\bin\drivers

Driver:	Signed?	Signature:	Valid?	SubmissionID:	Version:	OS list:
btusbflt.cat	Yes	WHQL	Yes	1378725		6.3.0.2500 XP Vista Win7
btwaudio.cat	Yes	WHQL	Yes	1392662		6.3.0.3820 Vista Win7
btwavdt.cat	Yes	WHQL	Yes	1385161		6.3.0.3400 Vista Win7
btwrchid.cat	Yes	WHQL	Yes	1385175		6.3.0.3400 Vista Win7
frmupgr.cat	Yes	WHQL	Yes	1368667		6.3.0.1750 XP Vista Win7
btwl2cap.cat	Yes	WHQL	Yes	1392745		6.3.0.3850 Vista Win7
bcbthid32.cat	Yes	WHQL	Yes	1350230		6.3.0.1500 Vista Win7
btwampfl.cat	Yes	WHQL	Yes	1398326		6.3.0.4400 Vista Win7
btwampsecfl.cat	Yes	WHQL	Yes	1394841		6.3.0.4010 Vista Win7
bcbtums-Vistax86-brcm.cat	Yes	WHQL	Yes	1378986		6.2.0.9411 Vista
bcbtums-Win7x86-brcm.cat	Yes	WHQL	Yes	1378986		6.2.0.9411 Win7

Folder: q:\BTW\btw1.2\bin\amd64\drivers

Driver:	Signed?	Signature:	Valid?	SubmissionID:	Version:	OS list:
btusbflt64.cat	Yes	WHQL	Yes	1378725		6.3.0.2500 XP Vista Win7
btwaudio64.cat	Yes	WHQL	Yes	1392662		6.3.0.3820 Vista Win7
btwavdt64.cat	Yes	WHQL	Yes	1385161		6.3.0.3400 Vista Win7
btwrchid64.cat	Yes	WHQL	Yes	1385175		6.3.0.3400 Vista Win7
frmupgr64.cat	Yes	WHQL	Yes	1368667		6.3.0.1750 XP Vista Win7
btwl2cap64.cat	Yes	WHQL	Yes	1392745		6.3.0.3850 Vista Win7
bcbthid64.cat	Yes	WHQL	Yes	1350230		6.3.0.1500 Vista Win7
btwampfl64.cat	Yes	WHQL	Yes	1398326		6.3.0.4400 Vista Win7
btwampsecfl64.cat	Yes	WHQL	Yes	1394841		6.3.0.4010 Vista Win7
Bcbtums-Vistax64-brcm.cat	Yes	WHQL	Yes	1378986		6.2.0.9411 Vista
bcbtums-win7x64-brcm.cat	Yes	WHQL	Yes	1378986		6.2.0.9411 Win7

BTW 6.3.0.4400

Resolved Defects

Major

BLTH00228839

Subsystem: Driver

Headline:

Need new PID to be added into filter driver btusbflt.inf

Release Note:

added pid/vid to btwampfl.inf file

BLTH00238708

Subsystem: USB

Headline:

add new pid/vid for HP 6.3 package

Release Note:

added pid/vid to btwampfl.inf file.

BLTH00261156

Subsystem: Driver

Headline:

Need new PID to be added into filter driver btusbflt.inf for Mavintec

Release Note:

added pid/vid to btwampfl.inf file.

BLTH00269354

Subsystem: Other

Headline:

update btwampfl.inf file

Release Note:

update btwampfl.inf file.

Resolved Defects

Major**BLTH00270431****Subsystem: Stack Server****Headline:**

Unable to send file using right click-> sendto option after HW off/on

Release Note:

sendto started before stackserver is done with service discovery. fix is for sendto to wait till service discovery is done

Resolved Defects

Minor**BLTH00261164****Subsystem: (UI) Bluetooth****Headline:**

"Cancel synchronization" button status does not change after synchronization complete.

Release Note:

Changed logic in close window event handler and UI Reset function.
